Your best partner in belting, also for the coming 20 years! www.trexrubber.com



T-REX REPAIR MATERIAL

T-REX SCREW SPLICE

Designed to make a quick belt splice

- The splice is flexible so T-Rex Screw Splice can be applied in installation with scraper.
- ✓ Smoother surface than most mechanical solutions.
- ✓ Quick and reliable belt splicing solution.
- ✓ Designed to be used without special belt maintenance tools.
- ✓ Installation is ready for production after belt splicing is ready (no curing time and no waiting time).





Splicing Material for making quick splices without vulcanization press or glue!



AVAILABLE TYPES		TS35	TS63	TS80
NQ	= Normal quality, Abrasion Resistant	NQ	NQ	NQ
HTR	= Heat Resistant quality, 200°C EPDM	HTR	HTR	HTR
OR	= Oil and grease Resistant quality	OR	OR	
STAINLESS	= Stainless Steel Screws	STAINLESS	STAINLESS	
Typical textile belts		EP250 EP 315 EP400	EP500 EP630 EP800	EP800 EP1000

Please contact our sales team for more information