

T-REX PROJECT INTERNATIONAL RUBBER NEWS

Your international partner
www.trexrubber.com

Project Mobile Crusher, Norway

Damage caused by misalignment conveyor belt
Conveyor Belt: Ripstop, width 1400 mm



We provided solution by installing a Tru-Trac® Flat Return Tracker
Challenge : limited space for installation
No space for belt to misalign



Tru-Trac® Flat Return Tracker

