

Project Concrete Mixing Plant, France

Problems misalignment of conveyor belt
Conveyor Belt : T-Rex Profile L44, width 650 mm



Solution: Tru-Trac® Flat Return Tracker



We provided our customer solution by installing Tru-Trac® Flat Return Tracker
Result : Straight running profiled conveyor belt and a satisfied customer

